Fe SSACIII

IMMEDIATE ACTIONS

Needle pricks, cuts or scratches

- Wash with soap and water for at least 5 minutes before rinsing.
- · Do not scrub or cause any bleeding.

Splashes in eyes

- **Rinse thoroughly** with plenty of clear running water for at least **5 minutes**, hold eyelids wide open, head tilted back and the affected eye looking downwards.
- Contact lenses tend to get washed away on their own, do not try to manually remove them.
- Do not use any collyre or eye solution.
- 3'i SkeUa`eg'fS` abZfS_ a'aY[efz



In any situation when **biological liquids and human tumor material** are used, apply the **BBVs protocol**.

IN ANY CASE

- **Declare the accident** (medical certificate required).
- Inform your safety manager immediately.
- All injuries are to be reported using the occupational health and safety logbook.
- Report all incidents to the **Occupational Health Doctor** for investigation and follow-up.
- Specify the **product in question** to search for the monoraph.
- Monitor the wound, its healing process in the weeks to come. Consult a doctor in case of inflammation or necrosis.

PROTECTION MEASURES

- Respect the proper laboratory rules.
- Limit the usage of sharp and cutting instruments.
- Use the personal protective gear equipment.
- Collect any potentially contaminated clothes and place them in a **closed plastic bag**.







Rédaction : SCMP - Création et réalisation : Audrey Raudin (DRH - MO) - MAJ september 2024